

कार्यपालन यंत्री लोक निर्माण विभाग (भ./स.) संभाग बैतूल (म.प्र.)
Web Site : www.mp.gov.in/pwdmp E-Mail : cepwdbetul@mp.nic.in
☎ 07141 - 238376, FAX No.-07141 - 238376

पत्र क्रमांक 2402 / तां.-45आर./ फिटनेश सर्टिफिकेट बैतूल, दिनांक 19/05/2022
प्रति,

✓ प्राचार्य
आर.डी. पब्लिक स्कूल
कालापाठा, जिला बैतूल (म.प्र.)

विषय :- भवन सुरक्षा प्रमाण-पत्र प्रदाय करने बाबत।

संदर्भ :- आपका पत्र दिनांक 22/04/2022

उपरोक्त संदर्भित पत्र के विषयांतर्गत मे लेख है कि आपके द्वारा चाहे अनुसार अनुविभागीय अधिकारी, लोक निर्माण विभाग उपसंभाग बैतूल द्वारा निरीक्षण किया गया। निरीक्षण के दौरान पाया गया कि उक्त भवन वर्तमान मे सुरक्षित है। सुरक्षा प्रमाण-पत्र वर्ष दिनांक 01/05/2023 तक की अवधि हेतु वैद्य होकर आपकी ओर 1 प्रति मे संलग्न प्रेषित है।

संदर्भ :- फिटनेश सर्टिफिकेट 1 प्रति मे।

कार्यपालन यंत्री
लो.नि.वि. (भ./स.) बैतूल संभाग
बैतूल (म.प्र.)

पृ.क्रमांक / तां.-45आर./ फिटनेश सर्टिफिकेट बैतूल, दिनांक / / 2022

प्रतिलिपि :-

अनुविभागीय अधिकारी, लोक निर्माण विभाग उपसंभाग बैतूल की ओर सूचनार्थ अग्रेषित।

सहपत्र :- शून्य।

कार्यपालन यंत्री
लो.नि.वि. (भ./स.) बैतूल संभाग
बैतूल (म.प्र.)

**INSPECTION REPORT OF SUB-ENGINEER P.W.D. (B&R) SUB-DIVISION
BETUL**

OFFICER REF :-

NAME OF BUILDING :- R.D. PUBLIC SCHOOL KALAPATHA NEAR KALICHATTAN BETUL(M.P)

INSPECTION DATE :- 02/05/2022

ABOVE MENTION BUILDING IS INSPECTED BY ME ON ABOVE MENTION DATE. IN PHYSICAL INSPECTION CONDITION OF VARIOUS ROOMS ARE GIVEN BELOW.

NEW BUILDING DETAILS

FLOOR	CONDITION OF ROOM	No. OF ROOM
GROUND FLOOR	GOOD CONDITION	12 Nos WITH TOILET
G-1 FLOOR	GOOD CONDITION	12 Nos WITH TOILET
G-2 FLOOR	GOOD CONDITION	11 Nos WITH TOILET
G-3 FLOOR	GOOD CONDITION	12 Nos WITH TOILET
G-4 FLOOR	GOOD CONDITION	12 Nos WITH TOILET

NOTE :- GROUND, G-1, G-2, G-3 HAS RCC ROOF AND G-4 HAS G.S. SHEET ROOFING.

OLD BUILDING DETAILS

FLOOR	CONDITION OF ROOM	No. OF ROOM
BASEMENT	GOOD CONDITION	10 Nos WITH TOILET
GROUND FLOOR	GOOD CONDITION	26 Nos WITH TOILET
G-1 FLOOR	GOOD CONDITION	22 Nos WITH TOILET
G-2 FLOOR	GOOD CONDITION	22 Nos WITH TOILET
G-3 FLOOR	GOOD CONDITION	22 Nos WITH TOILET
G-4 FLOOR	GOOD CONDITION	8 Nos WITH AUDITORIUM

NOTE :- BASEMENT, GROUND, G-1, G-2, G-3 HAS RCC ROOF AND G-4 HAS G.S. SHEET ROOFING.

HENCE PHYSICAL INSPECTION. IT IS FOUND THAT BUILDING STRUCTURE IS SAFE FOR USE IN EVEN CLIMATE CONDITION. AND REPORT SUBMITTED TO SUB-DIVISIONAL OFFICER TO FURTHER ACTION.

ENCLOSURE

M. Naidu
SUBENGINEER
P.W.D.(B/R) SUB DIVISION
BETUL

P. Sarve
SUBDIVISIONAL OFFICER
P.W.D.(B/R) SUB DIVISION
BETUL

c/s
[Signature]
EXECUTIVE ENGINEER
P.W.D.(B/R) DIVISION
BETUL